



Environmental Restoration Project

Area of Concern (AOC) No. 1073: Building 6580 Seepage Pit (TA-V)

ADS: 1295

Operable Unit: Septic Tanks and Drainfields

Site History	1
Constituents of Concern.....	1
Current Hazards	1
Current Status of Work	1
Future Work Planned	2
Waste Volume Estimated/Generated	2

Primary Contact: [Dick Fate](#)

Office Phone: 284-2568

Site History

Historical SNL/NM Facilities Engineering drawings indicate that this seepage pit is located approximately 50 feet west of the northwest corner of Building 6580, in a landscaped median in TA-V. It is assumed that this unit was abandoned in the early 1990s when the City of Albuquerque sanitary sewer system was extended into TA-III and TA-V. No other historical research has been conducted for this site.

Constituents of Concern

Constituents of concern for this site are unknown.

Current Hazards

No known surface hazards have been identified.

Current Status of Work

A field inspection was conducted at the site in July 1999 and the seepage pit was located and determined to still be intact at that time. To determine if environmental contamination is present beneath this system and in accordance with agreements reached with NMED personnel, sampling was conducted at this site. As shown on the site map, a single soil sample boring was drilled directly beneath the seepage pit in September 2002. Soil samples collected from this boring were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), polychlorinated biphenyls (PCBs), total cyanide, high explosive (HE) compounds, metals, and radionuclides.

Future Work Planned

This site may be selected for deeper environmental characterization sampling if analytical results from the shallow sampling indicate potentially significant contamination at depth.

Waste Volume Estimated/Generated

No environmental characterization or remediation waste has been generated at the site to date.

Information for ER Site 1073 was last updated Jan 23, 2003.