



Photonic Displacement Interferometry (PDI)

August 12, 2009


Leandra Boucheron
Mentor: Scott Jones




Introduction

- **Problem: How do you measure material response to radiation pulses?**
 - Constraints
 - Sample disturbance
 - Electromagnetic noise
- **Solution: Photonic Displacement Interferometry**
 - Summary of technique
 - Advantages


Interference of Light




+






+





==




==






System Basics








Reference and Shifted Beams









3X3 Coupler







Coupler Output





Data Analysis

- **THRIVE (Three Interferometer Velocimetry) Program**





Conclusion

- PDI Overview
- Questions?

